

Customer No.: TYROLPR

Invoice No.: 59556

# LOVELACE PUMP CO., INC.

9914 County M Argyle, WI 53504 FAX - 608-465-1114 lovelacepump@tds.net

### Invoice

Argyle - 608-465-3314 Dodgeville - 608-935-3581 Barneveld - 608-924-1815

New Glarus - 608-527-6100

Bill To: TYROL PROPERTIES

3487 BOHN RD. MOUNT HOREB, WI 53572 Job Site: SCOTT MCKAY

3506 BOHN RD.

MOUNT HOREB, WI 53572

Invoice Nur	Invoice Date			Invoice Due Date	Invoice Due Date			
5955	56		03/05/21			04/04/21		
Purchase Order Number Order I		Date Sales Person			Our Order N	Our Order Number		
	03/05	5/21	SCOTT LOVELACE		55916			
Quantity	Item Number		Description		Unit Price	Amount		
		SEPTIC INSPECTION WELL INSPECTION				200.00		
						150.00		
			RIA, NITRATE, & IC WATER SAMPLES			130.00		
			ON COMPLETED & TAKEN ON 03/02/21					
			Ir	voice subtotal		480.00		
			In	voice total		480.00		







# LOVELACE PUMP CO., INC.

9914 County M Argyle, WI 53504 FAX – 608-465-1114 lovelacepump@tds.net Argyle – 608-465-3314 Dodgeville – 608-935-3581 Barneveld – 608-924-1815 New Glarus – 608-527-6100

#### SEWAGE DISPOSAL/WATER SUPPLY INSPECTION REPORT

REQUESTING PARTY:

TYROL PROPERTIES LLC

**3487 BOHN RD** 

**MOUNT HOREB, WI 53572** 

PROPERTY ADDRESS:

SCOTT MCKAY

**3506 BOHN RD** 

MOUNT HOREB, WI 53572 DANE CTY. - VERMONT TWN.

#### **WATER SYSTEM**

A well inspection was completed by Lovelace Pump Company on 03/02/2021. This was an above ground visual inspection only (no components were pulled from the well and inspected). This well was drilled in 1964. Currently, the well is only 4" above grade. It is required to extend the steel well casing to a minimum of 12" above grade to meet the current Wisconsin well code. Also, this water system needs to have a sample faucet installed 12" above the floor, and the electrical wires at the wellhead need to be enclosed inside of conduit to meet the code. Lastly, it is recommended that and a pressure relief valve be installed.

#### SEE ATTCHED WATER SAMPLE SHEET

Bacteriological: Safe -- Nitrate: <0.03 mg/L as N (Safe)-- Arsenic: None Detected ug/L (Safe)

#### SEWAGE DISPOSAL SYSTEM

A septic inspection was completed by Lovelace Pump Co. on 03/02/2021. This was an above-ground inspection only. There was no effluent found above ground or evidence of any backup at the time of the inspection. This is a mound type system installed in 1984 for a three-bedroom house. This system is dry, and the tanks do not need pumping at this time. It is recommended to install locks and chains and warning labels over the septic tank lids; for safety and to meet the current code. Also, the septic alarm does not sound, only the light comes on, and the observation pipe on the tank does not have a cap. Lastly, there is a shallow line draining into the inspection part of the septic tank. It is unknown what this line is draining, but it should be relocated to the inlet side of the tank.

The undersigned cannot guarantee continued acceptability of the private waste disposal system and/or water supply due to unpredictable factors which could later determine the life or compliance of the system.

Company Name: Lovelace Pump Company

Address: 9914 County Road M. Argyle, WI 53504

Inspector: Scott Lovelace

Signature

Family Business Since 1910

Complete Water Systems • Complete Septic Systems • Pump Installation & Service • Well Drilling Available • Radio Dispatched Trucks • Livestock Waterers • Backhoe Service Interest will accrue at 18% per annum after 30 days.







## LOVELACE PUMP CO., INC.

9914 County M Argyle, WI 53504 FAX - 608-465-1114 lovelacepump@tds.net

Argyle - 608-465-3314 Dodgeville - 608-935-3581 Barneveld - 608-924-1815 New Glarus - 608-527-6100

#### **Existing Private Sewage System Inspection Report**

Contact Inf						形态的原金数		NAS DE		
Inspection Requested By TYROL PROPERTIES LLC							Telephone Number (608) 437-4135			
			City		State		ZIP Code			
3487 BOHN RD				MOUNT HO	WI		53572			
Property O	wner's Nan	ne					Teleph	Telephone Number		
SCOTT MC							1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Mailing Add	dress				City		State	State		
3506 BOHN RD			MOUNT HOREB		WI	WI				
Property Lo	cation			SECTION IS		HILLIAN STATE				Complete States
Fire Number Street or Road BOHN RD			□City ☑Town □Village County of VERMONT DANE			a de conseguir de conseguir de conse				
	1/4	Section	Township	Range E 💆	Year Installed	Currently O	ccupied?	Permit A	Available at	County?
SE	SE	28	7 N	6 W □	1984		No 🗆			
Comments and Recommendations										

A septic inspection was completed by Lovelace Pump Co. on 03/02/2021. This was an above-ground inspection only. There was no effluent found above ground or evidence of any backup at the time of the inspection. This is a mound type system installed in 1984 for a three-bedroom house. This system is dry, and the tanks do not need pumping at this time. It is recommended to install locks and chains and warning labels over the septic tank lids; for safety and to meet the current code. Also, the septic alarm does not sound, only the light comes on, and the observation pipe on the tank does not have a cap. Lastly, there is a shallow line draining into the inspection part of the septic tank. It is unknown what this line is draining, but it should be relocated to the inlet side of the tank.

	Sketch of Premises (not to s	cale)
Mound Drainfield	Barn	800 Gallon Pump Tank  3  Bedroom House
		Bohn Rd
	NORTH	

Certification and Disclaimer

I certify that the above information is true and correct to the best of my knowledge as observed on 03/02/2021. Operational aspects and observations reported are based on the conditions noted at the time of inspection. This inspection does not in any way guarantee or warrant the continued operation of the system described herein.

Family Business Since 1910

Date: Inspected by:

Complete Water Systems • Complete Septic Systems • Pump Installation & Service • Well Drilling Available • Radio Dispatched Trucks • Livestock Waterers • Backhoe Service

State of Wisconsin Department of Natural Resources dnr.wi.gov

### **Property Transfer Well and Pressure System Inspection**

Form 3300-221 (R 11/19)

**Notice:** Pursuant to ch. 280, Wis. Stats., and ch. NR 812, Wis. Adm. Code, this form shall be used to document any well and pressure system inspection conducted as part of a property transfer. Inspections are voluntary, and well owners are not required to bring systems into compliance as a result of the inspection. Inspectors must provide the completed form to the requester of the inspection. Do not send forms to DNR.

<b>Contact Informat</b>							情的意识		
Inspection Reques				Telephone Number					
TYROL PROPE				(608) 437-4135					
Mailing Address	City		State	ZIP C					
3487 BOHN RD Well Owner's Nam				MOUNT I	TOREB		WI		53572
SCOTT MCKA							i elepno	ne Numbe	r
Mailing Address				City			State	ZIP C	ada
3506 BOHN RD				MOUNT I	IORER		WI	E ZIF C	53572
Property Locatio		SAN PARAMETER		MOCIVI	TOKED				33372
Fire Number	Street or Roa	d		O City	• Town	) Village	County		
3506	BOHN RD				MONT	, ,	Dane		
1/4 1/4 1/4	Section	Township	Range E •	Latitude (DI	D, ex. 44.444	Longitud	e (DD, ex	x89.999)	WUWN
SE SE	28	07 N	6 w O						
Identified noncor	nplying featu	res (noted be	low with a chec	k mark)		特別。開發表			
1. Unused W	ell			13.	Nonpressi	ure Condui	t		
2. Stovepipe	or Thin-Walled	Well Casing		14.	] Hand Pum	пр			
3. Dug Well				15.	Offset Pur	np or Pipin	g Height	Above Ba	sement Floor
4. Buried Suc	tion Line			16.	Yard Hydr	ant			
5. Alcove (Su	bsurface Pump	room) or Pit		17.	Materials f	for Pump a	nd Suppl	y Piping	
6. Non-Walko	ut Basement o	r Below-Grade	e Crawl Space We	ell 18. 🗆	Flowing W	ell Installa	tion		
7. Poor Well	Casing Pipe Co	ondition		19.	Check Val	ve Locatio	n		
8. Contamina	ion Source les	s than minimu	ım separation dist	ance 20.	Well Cap	or Seal			
from well:				21.	Casing He	eight			
9. Well in Floo	dway or Flood	Fringe		22.	Electrical \	Wires at W	ellhead N	Not Enclose	ed in Conduit
10. Well at Ris	from Localize	d Flooding		23.	Sample Fa	aucet is Mis	ssing or N	Voncomplying	
11. Cross-Con	nection			24.	-11 22				Il terminating in
12. Driven Poir	it Well < 25 we	Il casing pipe	or installed after			dolomite,			
1-31-1991	with no well co	nstruction repo	ort	25.	] Extreme H	lealth/Safe	ty Hazaro	d	
Comments							San San San		
Pre-1991 D	riven Point Pip	e Depth < 25	feet		] Inaccessib	le or Difficu	ult Locatio	on for Futui	re Pump Work
☐ Well Construction Report Not on File or Unlocatable ☐ Non-Vermin-Proof Well Cap or Well Seal							ıI		
☐ Well Located in Special Well Casing Depth Area ☐ Unable to confirm whether well terminates in limeston							es in limestone,		
☐ Pre-1979 Two-Wire Submersible Pump dolomite, shale, quartz or granite ☐ Other:									
Evidence o	Some Corrosi	ion on Well Ca	asing Pipe	L	J Other.				
Inaccessibl	e or Difficult Lo	cation for Futi	ure Well Work						
Compliance Dete	rmination		1. 图片表示的						<b>与专门的</b>
Based on my perso	nal inspection o	of the real prop	erty, the well and	pressure sy	stem: (check	one)			
O Complies	vith NR 812, W	is. Adm. Code	Э						
<ul><li>Does not 0</li></ul>	omply with NF	R 812, Wis. Ad	dm. Code						
Complies with NR 812, Wis. Adm. Code, except that a more comprehensive search or additional research is needed to									
evaluate potential violations that may exist but are not fully identifiable as part of the basic visual inspection, such as:									
an unused well floodway/floodplain contamination source other:									
This form lists the visible conditions of the well and pressure system on the property at the time of inspection and does not imply or give any guarantee. Some features such as well cap, casing height or nonpressure conduit may comply for purposes of this inspection, but may require an upgrade the next time work is done on the well or pressure system.									
<u> </u>						ls .			
Signature of Licens	ed water Well	Driller or Pum	p Installer	Individual L		Date		Telephone	Number
Sent		- relea	AND THE RESERVE AND THE PARTY OF THE PARTY O	59	22	03/02/	2021	(608)	465-3314

Water Sample Collection Information Form	Do not use this form for Public Water Compliance Samples
Collection Date (MM/DD/YY)	ected By License # (pump installer/well driller)
3 2 Time: 11:30 AMPM	6353
31210	6333
Owners Name-	Owners Telephone Number
Owners Street Address 3 4 8 7 Buhn Rd	Well Address (Street or Legal Description)
City, State, Zip Code  Mount Horeb WI 5357	Townor City County
	Email Address (for electronic results)
Mail NameLOVELACE PUMP CO., INC	Based G. Sales, C. S. Comp.
Results Address 9914 CTY M	Prepaid: Bacteria
To: ARGYLE, WI 53504	Test(s) Requested
City State Zip Code	Bacteriological Nitrate
	Arsenic Other
Sampler Remarks, if needed:	Laboratory Use Only
	Bacteriological Approved Method Nitrate Approved Method
Private Sample Information Only	MMO-MUG (Colisure)
Reason for Test:	Membrane Filter 4500-NO3, SM 20th ed.
Annual Test Real Estate	Presence/Absence
Taste/Odor Previous Unsafe	Other
Other	Sample Rejection:
Sample Location:	Old Chlorine Present-CL
Bath. Tap Pressure Tnk. Tap	Overgrown Frozen-FR
Kitchen Jap Milk house	Turbidity Shipping Problem-SP
1 Other Bull of an	Laboratory Results:
Is Chlorine Present? Yes No	Bacteriological Interpretation:
Does the well serve the public? Yes No	SAFE (Coliform Absent)
Public #:	
Pump or Well Information Only	UNSAFE (Coliform Present) and:
*Results are Required to be submitted to DNR	Fecal/E. Coli Present
Reason for Test:	Fecal/E. Coll Absent
*Pump Work *New Well	
Well Construction Information	Arsenic:ug/L
Drilled Driven Point	Wisconsin Department of Health Services (DHS) recommends
JettedDug	that you stop using your water for drinking or food
Other:	preparation if Arsenic level is greater than
Driller (If new Well):	10 ug/L (ppb)
Lab Name: Lab Cert. #	
LV Laboratories LLC 105-443	Nitrate: ∠0-03 mg/L as N
Les Vondra	Department of Natural Resources state that water is
1015 S. Madison St	considered unsafe for infants under 1 year of age and
Lancaster, Wi. 53813	pregnant women when nitrate level is greater than 10 mg/L (ppm)
(608)723-4096 Email: <u>lesv@chorus.net</u>	Other: : mg/L or ug/L
Amount Paid: Cash Check	Date/Time Received: 3-3-21 9:20 A
Date Paid: Check No	Bacteriological Nitrate Sample No. Arsenic Sample No.
(F)	Date Reported
Staff Initials:	3-4-21
	Date Received by DNR
Samplin	ng Disclaimer
LV Laboratories, LLC reserves the right to reject any sample that is received.	
within 48 hours from the time the sample is collected. For additional sam	
of sample rejection. If sampler requests testing to be done upon notificati	
agrees to accept the sample(s) for testing and will qualify the results by o	
LV Labs will keep copies for five years before disposal.	à
International Control of the Control	LV Laboratories, LLC Date:

Water Sample Collection	Information Form			Do not use this form for Public Water Compliance Sam	anles
Collection Date (MM/DD/YY)		Collected	d By	License # (pump installer/well driller)	ipies
3,2,21	Fime: /1:30 (AM) PM	50	cott	6353	
Owners Name Urolf	roperties		Owners Teléphone Ni	umber	
Owners Street Address 3 487 BC	hnRd		Well Address (Street of Street)	or Legal Description)	
City, State, Zip Code  Mount Ho	neb WI 539	572	Fownor, City Ver n	nont County Dane	
Mail Name LOVELAC	E PUMP CO., INC		Email Address (for ele	ectronic results)	
Results Address 3	JI4 CIYM	7		Prepaid Bacterial en la	1 .
To: AHGY	LE, WI 53504		1	Test(s) Requested	
City	State Zip Code		Bacteriological	Nitrate	
Sampler Remarks, if needed:			Arsenic Lat	Other	Marriago Ma
			Bacteriological Approv	, ,	
Private Samp	le Information Only	***************************************		G (Colisure)	
Reason for Test:	<b>173</b>		Membrane Membrane	e Filter 4500-NO3, SM 20th ed.	
Annual Te		- £-	Presence/	Absence	
Other	Previous Onsa	are	Other_	mple Rejection:	
Sample Location:	22		Old	Chlorine Present-CL	
Bath. Tap	Pressure Tnk.	Тар	Overgrown		
Kitchen Ja			Turbidity	Shipping Problem-SP	
Is Chlorine Present?		_		poratory Results:	
Does the well serve the public? Yes	110	$\Rightarrow$	Bacteriological I	Interpretation: oliform Absent)	*
Public #:		Fri Sand Care	L SAL (GO	Smorth Absent)	
Pump or Well Infor			UNSAFE	(Coliform Present) and:	
	quired to be submitted to DNR			Fecal/E. Coli Present	
Reason for Test:				Fecal/E. Coli Absent	
	ork *New Well	- P	Arsenic:	1.00	
Drilled	Driven Point	1	- market distribution	Health Services (DHS) recommends	
Jetted	Dug <sup>-</sup>		that you stop using your w		
Other:	-		preparation if Arsenic leve		
Driller (If new Well): Lab Name:			10 ug/L (ppb)		
LV Laboratories LLC	Lab Cert, # 105-443		Nitrate:	The state of the s	
Les Vondra	100 440	1		mg/L as N sources state that water is	
1015 S. Madison St	#8			ants under 1 year of age and	
Lancaster, Wi. 53813				trate level is greater than 10 mg/L (ppm)	
(608)723-4096 En	nail: lesv@chorus.net		Other: :	mg/L or ug/L	
Amount Paid:	Cash Check	SECTION AND DESIGNATION OF THE OWNER, THE OW	Date/Time Received:	3-3-21	
Date Paid:	Check No	Ī	Bacteriological Nitrate S	Sample No. Arsenic Sample No.	
Staff Initials:		ī	Date Reported	1///2	
		Ī	Date Received by DNR	9/2(1)	
	Cam				
LV Laboratories, LLC reserves the rig	tht to reject any sample that is a	received n	Disclaimer	Dia/o) must be asset	
The san som the time san	ipie is collected. For additional	samples	rejections see shows	Complex will be supplied to	
or annibie refeetion. It samples reque	sts testing to be done upon not	ification of	sample rejection IVI	Laboratories, LLC	
advoces to accept the sample(s) tot fe	sting and will qualify the results	by dating	and initialing below.		
LV Labs will keep copies for fi	ive years before disposa		\/  _b	1.0	
		L	v Laporatories, LI	LCDate:	



1990 Prospect Ct., Appleton, WI 54914 \* 800-801-7590

LV LABS WATER 1001 S MADISON STREET LANCASTER, WI 53813 Home Owner

Q225A / TYROL PROPERTIES

Well ID/Address

3506 BOHN ROAD

Well City

Sample Location

**BOILER DRAIN** 

Lab#

557134

Lav T

Michael 7/1

000000

Collected By/Date SCOTT

3/2/2021

Analyte

Result

Units LOD LOQ Dil Dig Date Run Date Mthd Analyst QC Code

Inorganic Metals

Arsenic, Total

Report Date 04-Mar-21

None Detected ug/l

0.8 2.7 1

3/4/2021 3113B BF

of the

(as total As) Elevated arsenic levels are believed to cause skin cancer, and blood and nervous system disorders. The EPA and the WI DNR consider levels above 10 ug/L (parts per billion) in drinking water harmful.

LOD Limit of Detection

None Detected = Result was less than the LOD

LOQ Limit of Quantitation

Code

Comment

1

All laboratory QC requirements were met for this sample.

Laboratory Director