

COUNTRYSIDE GM AUTO GROUP  
N8167 KELLOM RD  
BEAVER DAM, WI 53916  
PH: 920-885-3301 OR 885-6182 FAX: 920-885-3379  
TAX# 11-3685517

REC-0250  
NOV 03 2017  
DANE COUNTY CLERK

\*\*\* SUPPLEMENT 1 \*\*\*

S1 04/07/2017 10:32 AM  
05/02/2017 09:07 AM

Owner

Owner: NATHAN R ANFINSON  
Address: 1027 MAIN ST APT 10  
City State Zip: HORICON, WI 53032-1576

Cell: (608)235-1371  
FAX:

Control Information

Claim #: 00445241037-0C  
Loss Date/Time: 04/06/2017 07:00 AM  
Deductible: \$500.00  
File #:

Insured Policy #: 2364472601  
Loss Type: Vandalism

Accounting #: commit

Ins. Company: American Family Mutual Insurance Company, S.I.

Insured: NATHAN R ANFINSON  
Address:

Work/Day: (608)235-1371

Inspection

Inspection Date: 04/07/2017 10:32 AM  
Primary Impact: Left Side  
Driveable: Yes

Inspection Type: Direct Repair Program  
Secondary Impact:  
Rental Assisted: No

Assigned Date/Time:  
First Contact Date/Time:

Received Date/Time: 04/11/2017 05:06 PM  
Appointment Date/Time: 04/12/2017 07:00 AM

Appraiser Name: Cheryl Smith  
Address: N8167 Kellom Road  
City State Zip: Beaver Dam, WI 53916

Appraiser License #:  
Work/Day: (920)885-3301  
FAX: (920)885-3379  
FAX:

Orig Appraiser Name: Tim Reilly  
Address: N8167 Kellom Road  
City State Zip: Beaver Dam, WI 53916

Appraiser License #:  
Work/Day: (920)885-3301  
Home/Evening: (920)885-3379  
FAX:

Repairer

Repairer: Countryside GM Auto Group  
Address: N8167 Kellom rd.  
City State Zip: Beaver Dam, WI 53916  
Email: bodyshop@countrysidegm.com  
License #: 11-3685517

Contact:  
Work/Day: (920)885-6182  
Work/Day: (920)885-3301  
FAX: (920)885-3379

Regulation ID:

Repair Start Date/Time: 05/01/2017 08:30 AM  
Repair Complete Date/Time: 05/01/2017 03:05 PM  
Target Complete Date/Time: 05/03/2017 05:30 PM

Vehicle Drop Off Date/Time: 05/01/2017 08:30 AM  
Vehicle Pick Up Date/Time: 05/02/2017 09:07 AM  
Days To Repair: 3

**Vehicle**

2015 Dodge Charger SE 4 DR Sedan  
 6cyl Gasoline 3.6  
 8-Speed Automatic

Lic.Plate: 10073  
 Lic Expire:  
 Prod Date:  
 Veh Insp# :  
 Condition:  
 Ext. Color: GRANITE CRYSTAL MET  
 Ext. Refinish: Two-Stage  
 Ext. Paint Code: LAU,PAU

Lic State: WI  
 VIN: 2C3CDXBG3FH925840  
 Mileage: 5,398  
 Mileage Type: Actual  
 Code: N3093B  
 Int. Color: Black  
 Int. Refinish: Two-Stage  
 Int. Trim Code: BBX9

**Options - AudaVIN Information Received**

1st Row LCD Monitor(s)	2nd Row Head Airbags	AM/FM CD Player
Air Conditioning	Aluminum Trim	Aluminum/Alloy Wheels
Anti-Lock Brakes	Auto Headlamp Control	Auxiliary Audio Input
Bucket Seats	Cargo/Trunk Net	Carpeting
Center Console	Chrome Grille	Compact Spare Tire
Cruise Control	Daytime Running Lights	Digital Clock
Driver Information Sys	Dual Airbags	Dual Zone Auto A/C
Electronic Compass	Floor Mats	Head Airbags
Heated W/S Wiper Washers	IPOD Control	Illuminated Visor Mirror
Intermittent Wipers	Keyless Access System	Keyless Entry System
Keyless Ignition System	LED Brakelights	Leather Shift Knob
Leather Steering Wheel	Lighted Entry System	MP3 Decoder
Overhead Console	Power Brakes	Power Door Locks
Power Drivers Seat	Power Mirrors	Power Steering
Power Windows	Projector Beam Headlamps	Pwr Accessory Outlet(s)
Rear Window Defroster	Rem Trunk-L/Gate Release	<b>Remote Starter</b>
<b>Reverse Sensing System</b>	Side Airbags	<b>SiriusXM Satellite Radio</b>
Split Folding Rear Seat	Stability Cntrl Suspensn	Strg Wheel Radio Control
Tachometer	Theft Deterrent System	Tilt & Telescopic Steer
Tinted Glass	Tire Pressure Monitor	Traction Control System
Trip Computer	Velour/Cloth Seats	Wireless Audio Streaming
Wireless Phone Connect		

*AudaVIN options are listed in bold-italic fonts*

**Damages**

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
<b>Front Doors</b>										
1	IT	31		Pnl,Front Door Outer LT	Partial Repair				2.0*	SM
2	L	31	#	Pnl,Front Door Outer LT	Refinish				3.2*	RF
					2.1 Surface					
					0.6 Two-stage setup					
					0.5 Two-stage					
				# = 10, 13						
				>> PARTIAL REFINISH WITH FULL CLEAR.						
3	RI	130		W/Strip,Belt Outer LT	R & I Assembly				0.2	SM
4	RI	229		Mirror,Outer R/C LT	R & I Assembly				0.9	SM
5	RI	227		Handle,Front Door Otr LT	R & I Assembly				0.2	SM
<b>Rear Doors</b>										
6	BR	33		Pnl,Rear Door Outer LT	Blend Refinish				1.2	RF



			0.8 Blend		
			0.4 Two-stage		
7	RI	325	W/Strip,Belt Outer LT	R & I Assembly	0.2 SM
8	RI	1216	Supt,RR Door Handle LT	R & I Assembly	0.8 SM

**Manual Entries**

9	EC	COVER VEHICLE EXTERIOR	Replace Economy	\$5.00*	SM
10	EC	HAZ. WASTE REMOVAL	Replace Economy	\$3.00*	SM
11	P	NOTE 1	Check		SM

>> NO ASSIGNMENT AT TIME OF ESTIMATE.

11 Items

**MC Message**

10	INCLUDES AUDATEX TIME TO CLEAR ENTIRE PANEL
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

**Estimate Total & Entries**

Other Parts		\$8.00	
Paint & Materials	4.4 Hours @ \$36.00	\$158.40	
Parts & Material Total			\$166.40
Tax on Parts & Material	@ 5.500%		\$9.15

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$56.00	2.3	2.0	4.3	\$240.80
Mech/Elec (ME)	\$78.00				
Frame (FR)	\$60.00				
Refinish (RF)	\$56.00	4.4		4.4	\$246.40

Labor Total		8.7 Hours	\$487.20
Tax on Labor	@ 5.500%		\$26.80
Gross Total			\$689.55
Less: Deductible			\$500.00-
Net Total			\$189.55
Less: Previous Net Total			\$189.55-
Net Supplement Total (Final Bill)			\$0.00

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53916 AMFAMCAPA  
 Recycled Parts Y/0/0 Zip Code: 00000 INV DATE: 04/11/2017  
 Rate Name Default

Audatex Estimating 8.0.134 S1 05/02/2017 09:13 AM REL 8.0.134 DT 04/01/2017 DB 05/01/2017  
 © 2017 Audatex North America, Inc.

1.5 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE

MANUFACTURER OF YOUR MOTOR VEHICLE.

### Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = RECYCLED PART
TE = Partial Replace Price	PM = Replace PXN Reman/Reblt	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2017 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.



## NOTICE

**DANE COUNTY ASSUMES NO LIABILITY TO  
USERS OF THE RAMP FOR DAMAGE TO VEHICLES,  
• LOSS OF PROPERTY, PERSONAL INJURIES, •  
OR OTHER DAMAGE LOSS OR INJURY FROM  
ANY CAUSE WHATEVER, AND ALL PERSONS USE  
THE RAMP AT THEIR OWN RISK. CO. ORD. 70.15**